


Stormwater Management and Erosion control

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESE

Location #: 312719

- Layers**
- Rule 411a PWS Conduces
 - Rule 411a Surface Water Internal Buffer
 - Rule 411a Surface Water Intermediate Buffer
 - Rule 411a Surface Water External Buffer
 - Brighton 1-189
 - Reservoirs (INT)
 - Exception Zone (INT)
 - Groundwater Sampling Zone (INT)
 - BMP Buffer Zone (INT)
 - Brighton 1-189 PWS Area
 - Wetland Fires (Updated Nightly) (INT)
 - WFIGS Current Incidents (Points)
 - WFIGS Current Perimeters
 - WFIGS 2021 Perimeters To Date
 - Floodplains (FEMA)
 - Environmental Sites
 - Air Quality (CDPHE)
 - Section, Township, & Range (PLSS)
 - Local Government Designees (LGDs)
 - Parks & Wildlife (CPW)
 - > 5 active locations per square mile
 - Energy Liasons
 - Districts
 - State Parks
 - State Trust Lands
 - State Wildlife Area
 - Wildlife Management Plan (verify with CPW)
 - Black Bear
 - Proposed 2023 High Priority Habitats (HPH)
 - High Priority Habitat (ALL)
 - Rule 1202 e NISO Habitats
 - Rule 1202 d Density Habitats
 - Rule 309 e 1 Other Consultation Habitats
 - High Priority Habitats (HPH) (Effective May 30, 2022)
 - High Priority Habitat (ALL)
 - Rule 1202 e NISO Habitats
 - Rule 1202 d Density Habitats
 - Rule 309 e 1 Other Consultation Habitats
 - National Wetlands Inventory (USFWS) (INT)
 - State Land (SLB)
 - Tribal Lands
 - Federal Land (BLM)
 - Master Title Plats (BLM) (INT)
 - Surface Features
 - Address Points - 2018 (INT)
 - Child Care Facilities (11/17/17) (INT)
 - Places
 - Parcels
 - Child Care Facilities Parcels (11/17/17) (INT)
 - Building Footprints - 2018 (INT)



- MAPGUIDE HELP**
- [Disclaimer](#)
 - [FAQs](#)
 - [Footprints](#)
 - [Map Layer Info](#)
 - [Map User Guide](#)
 - [Other Browsers](#)

This screen space is used for various map functions such as redlining and measuring distances, and will change depending on the function being used.

Need help? Map not working?

Please contact:
David Gates
david.gates@state.co.us
(303) 894-2100

NOTE: Many tablet and smart-phone browsers will not work with our interactive map. If you are having problems on a mobile device, please try using a computer-based browser instead.

Location Overview: Location is located in a High priority habitat area.

Section/Township/Range:12 8S96W

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESE
Location #: 312719



Photo #9739



Photo #9740

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESE
Location #: 312719



Photo #9743 Insufficient Stock piled soils BMPs.



Photo #9744 Insufficient Stock piled soils BMPs.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESE
Location #: 312719



Photo #9745 Location lacks stabilization.



Photo #9746 Location lacks stabilization.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESE
Location #: 312719



Photo #9747 Location lacks stabilization.



Photo #9749 Location lacks stabilization.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESE
Location #: 312719



Photo #9752 Insufficient tracking BMP at entrance to minimize the transport of sediment.



Photo #9753 Insufficient tracking BMP at entrance to minimize the transport of sediment.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESE
Location #: 312719



Photo #9754 Sediment has been transported off location.