


Stormwater Management and Erosion control

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESW.

Location #: 312696



Location Overview: Location is located in a high priority habitat area.

Section/Township/Range: 12 8S96W

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESW.
Location #: 312696



Photo #9770 From entrance to location.



Photo #9771 From entrance to location.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESW.
Location #: 312696



Photo #9772 Location lacks stabilization.



Photo #9773 Location lacks stabilization.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESW.
Location #: 312696



Photo #9774 Location lacks stabilization.



Photo #9775 Insufficient tracking BMP at entrance to location to Minimize the transport of sediment.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /12SESW.
Location #: 312696



**Photo #9776 Insufficient tracking BMP at entrance
to location to Minimize the transport of sediment.**