

Inspection Photos  
Location Name: Consolidation Unit 8 437627  
Facility ID: 437627



Photo #1 Location Sign



Photo #2 Mechanical Conditions & Oily Waste





Inspection Photos  
Location Name: Consolidation Unit 8 437627  
Facility ID: 437627



Photo #3 Mechanical Conditions & Meter not calibrated




Photo #4 Gas Meter Card shows no annual calibration



**Inspection Photos**  
**Location Name: Consolidation Unit 8 437627**  
**Facility ID: 437627**



**Photo #5 Unmarked Riser**



**Photo #6 Unmarked Riser**



**Inspection Photos**  
**Location Name: Consolidation Unit 8 437627**  
**Facility ID: 437627**



**Photo #7 Unmarked Riser**



**Photo #8 Unmarked Riser**





**Inspection Photos**  
**Location Name: Consolidation Unit 8 437627**  
**Facility ID: 437627**



**Photo #9 Mechanical Conditions & Oily Waste**



**Photo #10 Mechanical Conditions & Oily Waste**