

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2023

Submitted Date:

05/02/2023

Document Number:

708900383

FIELD INSPECTION FORMLoc ID 335076 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

27 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270355	WELL	PR	05/11/2004	GW	045-09533	CLOUGH RWF 322-29	PR
270359	WELL	PR	05/11/2004	GW	045-09532	CLOUGH RWF 22-29	PR
280050	WELL	PR	04/02/2006	GW	045-11162	CLOUGH RWF 522-29	PR
280051	WELL	PR	03/27/2006	GW	045-11163	CLOUGH RWF 21-29	PR
280052	WELL	PR	02/13/2006	GW	045-11164	CLOUGH RWF 422-29	PR
280053	WELL	PR	04/02/2006	GW	045-11165	CLOUGH RWF 423-29	PR
280054	WELL	PR	03/27/2006	GW	045-11166	CLOUGH RWF 23-29	PR
288284	WELL	PR	12/08/2006	GW	045-13183	CLOUGH RWF 512-29	PR
288285	WELL	PR	12/08/2006	GW	045-13182	CLOUGH RWF 412-29	PR
288286	WELL	PR	12/08/2006	GW	045-13181	CLOUGH RWF 312-29	PR

General Comment:

COGCC Inspection Report Summary

On 05/02/2023 at approximately 08:33 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up Inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 pad.
Location # 335076 in Garfield County Colorado.

Please refer to Inspection 708900108 conducted on 03/13/2023, 1 of 3 previous corrective actions has been completed.

Meter calibration info & Stormwater corrective actions have not been completed & CA dates remain the same.

Location is within High Priority Habitat area & Bald Eagle Nest & Roost Sites & within close proximity to NSO/Density Habitat areas.

Location is approximately 140 yards from the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Meter calibration info not conspicuously posted with a CA date of 03/29/2023

2. Stormwater - Culvert needs maintenance with a CA date of 03/29/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Chemical tanks - Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 10		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	03/29/2023
Type: Deadman # & Marked	# 7		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	270355	Type:	WELL	API Number:	045-09533	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	270359	Type:	WELL	API Number:	045-09532	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	280050	Type:	WELL	API Number:	045-11162	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	280051	Type:	WELL	API Number:	045-11163	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	280052	Type:	WELL	API Number:	045-11164	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	280053	Type:	WELL	API Number:	045-11165	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	280054	Type:	WELL	API Number:	045-11166	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	288284	Type:	WELL	API Number:	045-13183	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Facility ID: 288285 Type: WELL API Number: 045-13182 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

Facility ID: 288286 Type: WELL API Number: 045-13181 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						
				Material Handling And Spill Prevention		Chemical tanks & containments
		Culverts	Fail			Culvert needs maintenance
		Gravel				
		Compaction				
Gravel						
Ditches						

Comment: Culvert needs maintenance/sediment & debris reducing culvert capacity - culvert is approximately 160 ft east of location on spur road.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Date: 03/29/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment & Stormwater for observed compliance issues.	smelserw	05/02/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900384	Inspection 708900383 stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102176
708900385	Inspection 708900383 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102177