

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



May 2, 2023 at 9:22:36 AM
CO



May 2, 2023 at 9:22:40 AM
CO

Photo # 6692 From entrance to location

Photo # 6693 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 6694 Location



Photo # 6695 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



May 2, 2023 at 9:37:22 AM
CO



May 2, 2023 at 9:26:25 AM
CO

Photo # 6701 Location

Photo # 6696 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2241 From Inspection 708900110 conducted on 03/13/2023 Unmarked deadman



Photo # 6699 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 6703 Weeds/sapling in containment



Photo # 6706 Open ended pipe/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2266 From Inspection 708900110 conducted on 03/13/2023 Unused equipment

Photo # 6704 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2331 From Inspection 708900110 conducted on 03/13/2023 Meter calibration info not conspicuously posted

Photo # 6707 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2332 From Inspection 708900110 conducted on 03/13/2023 Meter calibration info not conspicuously posted



Photo # 6709 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 432-29 Pad

Location ID: 335494



Photo # 2226 From Inspection 708900110 conducted on 03/13/2023 Culvert needs maintenance

Photo # 6685 Culvert needs maintenance