

# Inspection Photos

API: 009-06134

Operator: SAMSON OIL COMPANY

Inspection Date: 5/3/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06134 | Date: 5/3/2023

## Inspection Photos



**Photo 1.** Approximately 100' northeast of the location is an abandoned pipeline user which must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06134 | Date: 5/3/2023

## Inspection Photos



**Photo 2.** Facing southwest toward the location which has been fenced off. There are areas that are bare of vegetation. Soils may be impacted preventing vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06134 | Date: 5/3/2023



## Inspection Photos



**Photo 3.** Facing south at the location. There are areas that are bare of vegetation. Soils may be impacted preventing vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06134 | Date: 5/3/2023

## Inspection Photos



**Photo 4.** Facing east at the west side of the location. There are areas that are bare of vegetation. Soils may be impacted preventing vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06134 | Date: 5/3/2023



## Inspection Photos



**Photo 5.** There is another pipeline riser that remains at the south side of the location that has not been removed



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06134 | Date: 5/3/2023