

Inspection Photos

API: 009-06268

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/3/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06268 | Date: 5/3/2023

Inspection Photos



Photo 1. Facing east toward the tank battery along the access road. The sign at the tank does not reflect current Operator or emergency contact INFO. If tank is not in use it must be removed. Tank berm is inadequate.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06268 | Date: 5/3/2023

Inspection Photos



Photo 2. Facing toward the wellhead. There is vegetation debris around the equipment which is a fire hazard. The sign at the well does not reflect current Operator or emergency contact INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 5/3/2023