

# Inspection Photos

API: 009-06081

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/3/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06081 | Date: 5/3/2023

## Inspection Photos



**Photo 1.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/3/2023

## Inspection Photos



**Photo 2.** Facing toward the open top tank which still does not have secondary containment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/3/2023



## Inspection Photos



**Photo 3.** The well sign does not comply with 605. Incorrect Operator Emergency number and missing information.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/3/2023

## Inspection Photos



**Photo 4.** Unused pipe riser still remains with no OOSLAT.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/3/2023