

**Inspection Photos**  
**Well Name: Ocoma 31-18**  
**API #05-123-14803**



**Photo #1 Well and Mangled fence**

**Photo #2 packing leak**