

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2023

Submitted Date:

05/05/2023

Document Number:

708300380

FIELD INSPECTION FORM

Loc ID 335205 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274661	WELL	PR	11/01/2018	GW	045-13377	CASCADE CREEK 620-24-43	PR
283588	WELL	PR	10/01/2021	GW	045-11965	CASCADE CREEK 697-20-53D	PR
283589	WELL	PR	11/01/2018	GW	045-11966	CASCADE CREEK 697-20-61D	PR

General Comment:

[COGCC Inspection Report Summary](#)

On 5/3/2023 at approximately 11:50, Compliance Inspector Matthew Morris conducted a follow-up inspection at LARAMIE ENERGY LLC, CC/0620-24-43 Pad at Location ID #335205 in Garfield County, Colorado.

FIR #708300173 corrective actions for wildlife protection equipment and gas meter calibration cards have been completed. Corrective actions for stormwater issues remain in effect. Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CONDENSATE	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 274661 Type: WELL API Number: 045-13377 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 283588 Type: WELL API Number: 045-11965 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 283589 Type: WELL API Number: 045-11966 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					Location lacks stabilization
Seeding						
Ditches						
Berms						
Gravel						
		Sediment Traps				
		Check Dams				
		Other	Fail			Insufficient vehicle tracking BMPs
Sediment Traps						
		Compaction	Fail			Lease road lacks stabilization
Other	Fail					Insufficient vehicle tracking BMPs
		Ditches				
		Gravel				
		Culverts				

Comment: 1) Location and lease road lack stabilization in muddy conditions with insufficient vehicle tracking BMPs in place to minimize transportation of sediment
2) Cut slope eroding onto location north of tank battery (reference FIR #708300173)

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002

Date: 03/17/2023

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	414405	1630654	
	414405	400390399	
	414405	400390399	
	414398	1630648	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300381	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6106166