

# Interim Reclamation and Stormwater Inspection

Date: 05/03/2023

Operator: FUNDARE RESOURCES OPERATING  
COMPANY LLC - 10773

Location ID: 438806

Inspection Document #: 708200221

Weld County, CO

Lot 3 Section 30 T10N R58W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806





**Photo 1.** Faded/cracked/peeling tank label will need to be replaced. Additionally, unused wires were observed next to tank and are now considered trash and will need to be disposed of, or removed off location.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photos 2 & 3.** Trash was observed throughout the location and will need to be disposed of. Operator shall self inspect the entire location for trash as these photos are only examples of trash observed during this inspection.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photos 4 & 5.** See comments in Photos 2 & 3.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 6.** See comments in Photos 2 & 3.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 7.** It appears the Operator has performed reclamation activities, however, the majority of the interim areas are not progressing towards Rule 1003 standards. Non-uniform vegetation cover resulting in areas of bare soil was observed throughout the location.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 8.** Facing east from the eastern side of the location; see comments in Photo 7.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 9.** Facing west from the southern side of the location; see comments in Photo 7.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 10.** Facing west from the western side of the location; see comments in Photo 7.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 11.** Facing north from the western side of the location; see comments in Photo 7.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 12.** Facing southeast from the northwestern side of the location; see comments in Photo 7. Evidence of road base was seen in this northwestern corner of the interim areas (red arrow); all road base material shall be removed and voids filled with topsoil as part of the reclamation process.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 13.** Facing north from the northern side of the location; see comments in Photo 7.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 14.** Facing east from the northern side of the location; see comments in Photo 7.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 15.** Tumbleweed debris and undesirable plant species observed on location; Operator shall implement a weed management program to control undesirable plant species during the next local growing season.

Inspection Photos  
Location Name: Razor 30L Pad  
Location ID: 438806



**Photo 16.** See comments in Photo 15.