

# Construction and Stormwater Inspection

Date: 05/03/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 481827

Inspection Document #: 708200224

Weld County, CO

NENW Section 34 T10N R59W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 1.** Facing northeast from the new access road entrance. At the time of this inspection, it did not appear topsoil had been salvaged from the access road with evidence of some grubbing having occurred. An approved copy of the From 2A was also not posted on location at the time of this inspection.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



Photo 2. See comments in Photo 1.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 3.** Grubbing pictured along the new access road portion; see also comments in Photo 1.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 4.** Facing northeast from an existing access road. The access road appears to have been grubbed and widened during the construction process.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 5.** Facing east from the northwest corner of the pad construction. Photo illustrates topsoil salvage operations and fugitive dust (red arrow) that was observed at the time of this inspection. Also pictured, a temporary stormwater BMP (ditch and berm) appears to have been installed during the construction phase of the location.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 6.** Close up photos of fugitive dust occurring from topsoil salvage.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 7.** Facing southwest from the northeast corner of the location. See comments in Photo 5.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 8.** Facing south towards the topsoil stockpile. A future inspection will be conducted to ensure all topsoil has been salvaged from the location and that stockpiles are stabilized against wind and water erosion.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 9.** Facing west from the southeast corner of the location. See comments in Photo 5.

Inspection Photos  
Location Name: Peanut Fed 3403  
Location ID: 481827



**Photo 10.** Facing northeast from the southwest corner of the location. See comments in Photo 5.