

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2023

Submitted Date:

05/02/2023

Document Number:

702501241

**FIELD INSPECTION FORM**Loc ID 314246 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name        | Phone          | Email                         | Comment |
|---------------------|----------------|-------------------------------|---------|
| Kellerby, Shaun     | (970) 712-1248 | shaun.kellerby@state.co.us    |         |
| Sanford, Anita      | (970) 551-8313 | Anita.Sanford@scoutep.com     |         |
| Johnson, Mike       |                | Mike.Johnson@scoutep.com      |         |
| Patterson, Chris    |                | Chris.Patterson@scoutep.com   |         |
| Regulatory, Rangely |                | RangelyRegulatory@scoutep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 228118      | WELL | PR     | 12/01/2021  | OW         | 103-01035 | CARNEY C T 14-34 | PR          |

**General Comment:****COGCC Inspection Report Summary**

On Tuesday, 05/02/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the Carney C T 14-34 well, Location #314246, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority/NSO/Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to FIRR #403369756 submitted by Operator for Corrective Action from Inspection #702500968 on 3/7/23.

While there during normal production operations the following compliance issue was observed:

1. Insufficient BMPs to control vehicle tracking.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

Comment: (970) 675-3700 / 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| Type: Ancillary equipment | # 1                                     |       | corrective date |
| Comment:                  | Chemical tank on containment            |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Deadman # & Marked  | # 6                                     |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Submersible Pump    | # 1                                     |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Bradenhead          | # 1                                     |       |                 |
| Comment:                  | Accessible with valve. Gauge installed. |       |                 |
| Corrective Action:        |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                      |                  |                       |            |                  |
|----------------------|------------------|-----------------------|------------|------------------|
| Inspected Facilities |                  |                       |            |                  |
| Facility ID: 228118  | Type: WELL       | API Number: 103-01035 | Status: PR | Insp. Status: PR |
| Producing Well       |                  |                       |            |                  |
| Comment:             | Submersible pump |                       |            |                  |
| Corrective Action:   |                  |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms            |                 |                         |                       |  |                          |         |
|                  |                 | Culverts                |                       |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention |                          |         |
|                  |                 | Ditches                 |                       |  |                          |         |

Comment: [Insufficient BMPs to control vehicle tracking.](#)Corrective Action: [Provide proper Stormwater BMPs for vehicle tracking to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Date: 06/02/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403391942    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102178">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102178</a> |
| 702501242    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102173">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102173</a> |