

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2023

Submitted Date:

05/02/2023

Document Number:

708300367

FIELD INSPECTION FORM

Loc ID 210985 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments5 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
ENERGY, VISION		mco@visionenergy.biz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323851	LOCATION	AC	03/01/2021		-	SOUTH SHALE RIDGE-68S98W 7NWSE	AC

General Comment:[COGCC Inspection Report Summary](#)

On 5/2/2023 at approximately 10:50, Compliance Inspector Matthew Morris conducted an on-site inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE at Location ID #323851 in Garfield County, Colorado.

Corrective actions from FIR #708300186 have not been completed and remain in effect.
 During the inspection, the following compliance issues were observed:

- 1) Weeds have encroached on all production equipment
- 2) Unused equipment on location
- 3) Gas meter calibration record not conspicuously posted
- 4) Tank battery berm permeability inadequate due to weed growth
- 5) Inadequate stormwater BMPs; refer to stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/(970) 858-8550		
Corrective Action:		Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds have encroached all production equipment on location.		
Corrective Action:	Remove weeds to comply with Rule 606	Date:	03/21/2023
Type	STORAGE OF SUPL		
Comment:	Unused equipment stored on location		
Corrective Action:	Remove unused equipment to comply with Rule 606	Date:	06/02/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration record not conspicuously posted		
Corrective Action:	Display legible gas meter calibration record in a conspicuous location to comply with Rule 430.d.(2)	Date:	03/24/2023

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berm permeability insufficient due to weed growth			
Corrective Action:	Repair berm to comply with Rule 603.o			Date: 04/14/2023

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 323851 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Gravel				
		Compaction				
		Culverts				
		Ditches				
		Other	Fail			Insufficient vehicle tracking BMPs
Berms						

Comment: Insufficient vehicle tracking BMPs in place on access road to minimize transportation of sediment

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002

Date: 05/17/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403391977	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102239
708300368	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102238