

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/28/2023

Submitted Date:

05/04/2023

Document Number:

700300561

**FIELD INSPECTION FORM**

Loc ID 333984 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,	970-563-4000	maralextech@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297995	WELL	PR	12/01/2019	CBM	067-09621	ARTFGANCE 33-7-14 2A	WK
298106	WELL	PR	10/01/2020	CBM	067-09623	ARTFGANCE 33-7-14 3C	UN

**General Comment:**

On Friday 4/28/23, SW Compliance Supervisor was driving in area and observed rig on one of the wells on location. As of 1 PM no electronic Form 42 notice of move in rig up has yet been submitted by operator as required by Rule 405.e

**Inspected Facilities**

Facility ID: 297995 Type: WELL API Number: 067-09621 Status: PR Insp. Status: WK

Facility ID: 298106 Type: WELL API Number: 067-09623 Status: PR Insp. Status: UN

**Workover**

Comment: Appears workover rig was on 2A well

Corrective Action: Retractively Submit electronic Form 42 for date rig nmoved onto location per Rule 405.e Date: 05/05/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403394327	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6104493">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6104493</a>
700300562	workover rig on location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6104490">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6104490</a>