


LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



Wellhead – Photo #03114



Separator – Photo #03118



LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



Tank Battery – Photo #03120



NW Corner of Location – Photo #03110



LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



SW Corner of Location – Photo #03111



SE Corner of Location – Photo #03112

LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



NE Corner of Location – Photo #03113



Location Lacks Stabilization – Photo #03117

LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



Location Lacks Stabilization – Photo #03119



Cut Slope Eroding onto Location – Photo #03123

LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03124**



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03125**

LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



Access Road Degradation – Photo #03093



Erosion Through Access Road – Photo #03095

LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



Insufficient BMP on Access Road – Photo #03096



Access Road Erosion/Degradation – Photo #03097

LARAMIE ENERGY LLC, Horseshoe Canyon/4-28

Location # 312739



Rill Erosion Through Access Road – Photo #03103



Erosion from Access Road/Sediment Trap Needs Maintenance – Photo #03104