

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2023

Submitted Date:

05/11/2023

Document Number:

708900456

FIELD INSPECTION FORMLoc ID 335210 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211565	WELL	PR	06/01/2011	GW	045-07325	CLOUGH RMV 94-21-H	PR
258168	WELL	PR	02/01/2001	GW	045-07623	CLOUGH RMV 233-28	PR

General Comment:**COGCC Inspection Report Summary**

On 05/10/2023 at approximately 09:31 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 pad.
Location # 335210 in Garfield County Colorado.

Please refer to Inspection 708900405 conducted on 05/04/2023, previous corrective actions have not been completed.
Location is within High Priority/Density Habitat areas & within close proximity to NSO Habitat & Bald Eagle Roost site.
Location is approximately 590 yards from the Colorado River.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Meter calibration info not conspicuously posted with a CA date of 04/20/2023
2. Two open cellars/wildlife hazard with a CA date of 05/09/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead signs weathered & cracking but still legible		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	2 open cellars on lease road		
Corrective Action:	Operators will prevent & minimize adverse impacts to wildlife resources.	Date:	05/09/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe rail fence & hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 5		
Comment:	Marked		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	04/20/2023
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Taylor plugs located on all bradenhead, all bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211565	Type:	WELL	API Number:	045-07325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	258168	Type:	WELL	API Number:	045-07623	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse in some areas
Compaction						
Slope Roughening						
		Compaction				
		Gravel				Sparse in some areas
Rip Rap						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Housekeeping & Equipment for observed compliance issues.	smelserw	05/10/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900457	Inspection 708900456 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6111499