

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2023

Submitted Date:

05/11/2023

Document Number:

707800351

## FIELD INSPECTION FORM

 Loc ID: 324592  
 Inspector Name: Ramsey, Scott  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 46290  
 Name of Operator: KP KAUFFMAN COMPANY INC  
 Address: 1700 LINCOLN ST STE 4550  
 City: DENVER State: CO Zip: 80203
**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212079	WELL	PR	07/01/2019	OW	057-05131	DWINELL 3	PR

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 5/9/2023, I, Inspector Scott Ramsey, conducted a routine inspection at KPK Dwinell 3, at Location # 324592 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Some evidence of storm water controls to prevent sediment migration, waddles not installed properly. No evidence of tracking BMP's to prevent sediment from location being transported from location.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/303-825-4822		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	05/19/2023

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

		#		corrective date
Type: Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Type: Other		# 1		
Comment:	Oil well head			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 212079 Type: WELL API Number: 057-05131 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					

Comment: 1. Some evidence of storm water controls to prevent sediment migration, waddles not installed properly. No evidence of tracking BMP's to prevent sediment from location being transported from location.

Corrective Action: Install, maintain or repair required BMPs

Date: 06/23/2023

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800357	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6111562">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6111562</a>