

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2023

Submitted Date:

05/05/2023

Document Number:

690204187

**FIELD INSPECTION FORM**Loc ID 321010 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
GEORGE KELLY		envexbaca@aol.com	
Welsh, Brian		brian.welsh@state.co.us	
Levengood, John		jlevengood07@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205764	WELL	PR	04/01/2015	GW	009-06176	STATE OF COLORADO 1-16	RI

**General Comment:**

On 5/3/2023, Ryan Costa conducted a Location Inspection.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	There is no well sign posted at the wellsite.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/05/2023
Type	TANK LABELS/PLACARDS		
Comment:	The tank label does not comply with 605. Missing tank NFPA labeling and missing INFO.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/05/2023

**Emergency Contact Number:**

Comment:	No emergency contact number posted.		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	There is still boards and pipe llaying on the ground. Previous CA not completed.		
Corrective Action:	Comply with Rule 606	Date:	12/10/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1	200 BBLS	FIBERGLASS AST		,	
Comment:	Previous inspection noted tank was not in use. Tank needs to removed from location. Previous corrective action not completed.					
Corrective Action:	Comply with Rule 606					Date: 12/10/2021

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	There is no secondary containment at the tank to contain a spill. The tank needs to be removed if not in use or secondary containment needs to be installed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: 06/02/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403395243	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105558">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105558</a>
690204188	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105551">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105551</a>