

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

FOR OFFICE USE			
ET	FE	UC	SE
		EA	

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <u>Injection Well</u>		5. LEASE DESIGNATION & SERIAL NO.	
2. NAME OF OPERATOR Brandly Oilman Consultants, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 1333 W. 120th Ave., #306, Westminster, CO 80234		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface NW/SE Sec. 32-7N-52W At proposed prod. zone Same		8. FARM OR LEASE NAME Dune Ridge	
14. PERMIT NO. Unable to locate.		9. WELL NO. 6-WI	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT Dune Ridge	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 32-7N-52W	
		12. COUNTY LOGAN	13. STATE COLO.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work As soon as possible.

* Must be accompanied by a cement verification report.

To plug and abandon the above well. Shoot off and pull casing ²⁵ at about 3800 feet. Cover perforations with sand. Set 5 sx. plug on sand. Set 20 sx. plug in and out of surface casing. Set 5 sx. plug at surface. Cut off plug and weld cap on surface. Donnelly Casing Pulling to do the work.

or: Cover perforations with sand. Set 5 sx. plug on sand. Set 15 sx. plug @ surface. Cut off and weld cap on surface.

RECEIVED

MAY 05 1989

COLO. OIL & GAS CONS. COMM.



00220450

19. I hereby certify that the foregoing is true and correct

PRINT Larry Brandly

SIGNED Larry Brandly TITLE President

DATE April 24, 1989

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE SUPR. PETROLEUM ENGINEER
Oil & Gas Cons. Comm.

DATE 5/15/89