

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2023

Submitted Date:

05/16/2023

Document Number:

708900502

FIELD INSPECTION FORMLoc ID 324047 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211569	WELL	PR	12/13/1998	GW	045-07329	CLOUGH RMV 93-21	PR

General Comment:**COGCC Inspection Report Summary**

On 05/16/2023 at approximately 10:21 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 pad.

Location # 324047 in Garfield County Colorado.

Please refer to Inspection 708900244 conducted on 04/07/2023, 2 of the 3 previous corrective actions have been completed.

Location is within High Priority/Density Habitat areas.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Meter calibration info not conspicuously posted with a CA date of 04/17/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.		Date: 04/17/2023
Type: Bradenhead	# 1		
Comment:	Taylor plug & pressure transducer located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	Marked		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211569	Type:	WELL	API Number:	045-07329	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Gravel						Sparse
Compaction						Light compaction in some areas
		Gravel				Sparse
		Compaction				

Comment: Location appears to have been bladed or dragged.

Location appears to have some gravel throughout the location with areas of light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

No other observed BMP's

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to equipment for observed compliance issue.	smelserw	05/16/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900503	Inspection 708900502 Stomwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6116498
708900504	Inspection 708900502 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6116499