

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NENW

Location #334903



NE Corner of Location – Photo #03364



SE Corner of Location – Photo #03365

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NENW

Location #334903



SW Corner of Location – Photo #03366



NW Corner of Location – Photo #03367

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NENW

Location #334903



Wellheads – Photo #03369



Separators – Photo #03375

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NENW

Location #334903



Tank Battery – Photo #03377



Location Lacks Stabilization – Photo #03368

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NENW

Location #334903



**Rill Erosion Transporting Sediment Off-Location –
Photo #03372**

**Rill Erosion Transporting Sediment Off-Location –
Photo #03374**

TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NENW

Location #334903



Site Degradation from Plow Causing Sediment Transportation and Lack of Stabilization – Photo #03376



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03381