

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2023

Submitted Date:

05/10/2023

Document Number:

696204927

FIELD INSPECTION FORMLoc ID 322318 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 22370

Name of Operator: D & G ROUSTABOUT SERVICE

Address: 765 S 1/2 ROAD

City: MACK State: CO Zip: 81525

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	
		terrelloil@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210269	WELL	SI	01/01/2019	GW	045-06025	WEST SALT CREEK-FEDERAL 1-7	RI
322318	LOCATION	AC			-	WEST SALT CREEK-FEDERAL-66S103W 7NESW	RI

General Comment:

On 5/8/2023, Reclamation Specialist Trujillo inspected D&G Roustabout Services West Salt Creek Federal 1-7 Location in Garfield County, Colorado.

Records show well is Fee Surface, Federal Mineral.

Location is within an Aquatic Native Species Conservation Waters buffer zone.

This inspection is a follow-up to Inspection Nos. 696204012 and 696204445, to document compliance with the following corrective action:

- Equipment, weeds, waste and trash requirements
- Secondary containment

This inspection is also a follow-up to Resolution #403262667 stating corrective actions have been completed.

It was observed in this inspection that the well has been Plugged and Abandoned.

The following new compliance issues were observed during this inspection:

- Final Reclamation; removal of surface equipment.
- Protection of soil stockpiles
- No Form 6(s) on file.

Refer to the "Location" and "Reclamation" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Undesirable Plant Species not observed at time of inspection.

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

WELLHEAD

Comment: Wellhead excavation has been fenced.

Corrective Action:

Date:

Equipment:

corrective date

Type: Other

#

Comment:

Wellhead:

Well has been P&Ad- Inspection #693805314 indicates well was plugged by 12/21/2022.

Pursuant to Rule 435.b.(1), Within 30 days after abandonment, the Form 6, Well Abandonment Report – Subsequent Report of Abandonment will be filed with the Director.

Unable to find records of a Form 6 "Subsequent Report of Abandonment" being submitted- Form 6(s) was required by 1/2023.

Corrective Action: Comply with Rule 435.b.(1)

Date: 05/17/2023

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

Comment: Tank at battery has been removed.

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No					
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	210269	Type:	WELL	API Number:	045-06025	Status:	SI	Insp. Status:	RI
Facility ID:	322318	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment _____

Soil stockpiles due to excavation activities at the well observed.

It was observed in this inspection that BMPs to minimize erosion and sediment transport from the soil stockpiles are missing or insufficient.

Corrective Action _____

Comply with Rule 1002.f and 1002.c.

Date **05/12/2023**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Well has been P&Ad- Inspection #693805314 indicates well was plugged by 12/21/2022.

It was observed in this inspection that surface equipment, risers, etc... have not been removed from the Location.

Pursuant to Rule 1004.a, all debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well; surface equipment required removal by 3/2023

Corrective Action:

Comply with Rule 1004.a and remove all debris, abandoned gathering line risers and flowline risers, and surface equipment.

Date **06/10/2023**

Overall Final Reclamation

FailWell Release on Active Location ☐Multi-Well Location ☐**COGCC Comments**

Comment	User	Date
Form 27(i) #403288872 for Facility Closure submitted 1/30/2023. Location non-cropland. Pursuant to 1004.a, final reclamation activities are required to be completed within 12 months of Well facility closure.	trujilloam	05/10/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403399751	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110360
696204928	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110347