

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2023

Submitted Date:

05/10/2023

Document Number:

696304866

FIELD INSPECTION FORMLoc ID 470277 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
470277	Location	AC			-	Seyfried 63N62W1SESW	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced Water Tank - Capacity Label appears to have faded; no longer visible. STILL remains; Corrective Action date remains the same. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/21/2023

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Separator. Tags appear to have Weathered/Broken off. STILL remains; Corrective Action date remains the same. See photos		
Corrective Action:	Comply with Rule 606	Date:	03/23/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 470277 Type: Location API Number: - Status: AC Insp. Status: AC**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI - Shut-In at the time of this Inspection

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine Field Follow-Up Inspection. Unmarked Risers STILL at Separator. Water Tank Capacity STILL faded</u>	petrie	05/10/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403400086	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110712
696304867	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110700