

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2023

Submitted Date:

05/10/2023

Document Number:

696304868

**FIELD INSPECTION FORM**Loc ID 406271 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 41385

Name of Operator: HS RESOURCES INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wold, Reed		reed.wold@state.co.us	
,		cogcc@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
406271	LOCATION	CL			-	STATE-63N62W 12SWNE	

**General Comment:**

Taknk Battery Inspection ONLY

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser by Gas Meter		
Corrective Action:	Comply with Rule 606	Date:	06/30/2023
Type	OTHER		
Comment:	Unused Equipment on Location: Tank, Separator, and pipe. See photos		
Corrective Action:	Comply with Rule 606	Date:	06/30/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	No berm, Tank not hooked up				
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					



**Inspected Facilities**Facility ID: 406271 Type: LOCATION API Number: - Status: CL Insp. Status: **Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: 

Comment: Well State 1-12 (API 05-123-08140) has been Plugged and Abandoned. Tank Battery that Serves State 2-12 (API 05-123-16623) has been Decommissioned; equipment STILL remains on Location. Further Inspections from COGCC Reclamation will flow this Inspection

Corrective Action:  Date: **COGCC Comments**

Comment	User	Date
Routine Field Inspection. Well State 1-12 (API 05-123-08140) has been Plugged and Abandoned. Tank Battery that Serves State 2-12 (API 05-123-16623) has been Decommissioned; equipment STILL remains on Location. Further Inspections from COGCC Reclamation will flow this Inspection	petrie	05/10/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403400087	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110713">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110713</a>
696304869	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110701">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110701</a>