

TEP ROCKY MOUNTAIN LLC, UNION-67S96W/2SENE

Location #334692



SW Corner of Location – Photo #03443

NW Corner of Location – Photo #03444

TEP ROCKY MOUNTAIN LLC, UNION-67S96W/2SENE

Location #334692



NE Corner of Location – Photo #03445

SE Corner of Location – Photo #03446

TEP ROCKY MOUNTAIN LLC, UNION-67S96W/2SENE

Location #334692



Wellhead Fencing Not Serviceable – Photo #03448

Separators – Photo #03455

TEP ROCKY MOUNTAIN LLC, UNION-67S96W/2SENE

Location #334692



Tank Battery – Photo #03456

Location Lacks Stabilization – Photo #03453

TEP ROCKY MOUNTAIN LLC, UNION-67S96W/2SENE

Location #334692



Location Lacks Stabilization – Photo #03454

Location Lacks Stabilization – Photo #03460

TEP ROCKY MOUNTAIN LLC, UNION-67S96W/2SENE

Location #334692



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03461

Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03462