

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2023

Submitted Date:

05/18/2023

Document Number:

697602086

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Ahmadian, Alexander On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Graber, Nikki		nikki.graber@state.co.us	
Meis, Craig		cmeis@kpk.com	<a href="#">KPK Environmental</a>
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241696	WELL	SI	06/01/2021	OW	123-09485	SUCKLA-BROWN UNIT 17	EI

**General Comment:**

This is an environmental inspection in response to Complaint Document Number 403402942. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Incident information:**

Spill Discovery Date: 10/1/2020

Days open: 959 days

Last report: 11/9/2022, operator is out of compliance with approved quarterly reporting schedule and rule Rule 913.e.(3), the next quarterly report was due 2/7/2023

Current site status: Impacts in situ, monitoring wells installed

**Location**

Overall Good:

Emergency Contact Number:

Comment: Signage at header is faded but legible.

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type UNUSED EQUIPMENT

Comment: Fencing and other unused equipment have been left onsite.

Corrective Action: Comply with Rule 606.

Date: 05/25/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type TANK BATTERY

Comment: Fencing around the tank battery is adequate.

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 241696 Type: WELL API Number: 123-09485 Status: SI Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: Monitoring wells have been installed around the header.

Corrective Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602087	Photo Documentation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6118859">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6118859</a>
697602088	Complaint	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6118860">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6118860</a>