

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905



SE Corner of Location – Photo #03527



SW Corner of Location – Photo #03528

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905



Wellheads – Photo #03529



Separators – Photo #03535

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905



Tank Battery – Photo #03539



Lease Road Degradation/Transportation of Sediment from Lease Road – Photo #03534

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905



Rill Erosion On Lease Road – Photo #03533

Rill Erosion Transporting Sediment from Location – Photo #03538

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWSE

Location #334905



**Rill Erosion Transporting Sediment from Location –
Photo #03541**



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03542**