

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location #324021



SE Corner of Location – Photo #03563



SW Corner of Location – Photo #03564

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location #324021



NW Corner of Location – Photo #03565

NE Corner of Location – Photo #03566

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location #324021



Wellhead – Photo #03567



Unprotected Soil Stockpile – Photo #03571

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location #324021



Unprotected Soil Stockpile – Photo #03572



Location Lacks Stabilization – Photo #03573

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1SWNW

Location #324021



Rill Erosion Transporting Sediment Across Access Road – Photo #03575



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03574