

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2023

Submitted Date:

05/19/2023

Document Number:

701103704

**FIELD INSPECTION FORM**Loc ID 324267 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271103	WELL	PR	03/13/2013	GW	045-09835	SHDELER 31-11D (531E)	EG

**General Comment:**

Flowline inspection

**Inspected Facilities**Facility ID: 271103 Type: WELL API Number: 045-09835 Status: PR Insp. Status: EG**Flowline**

#1	Type:	1 of Lines
----	-------	------------

Flowline Description

Flowline Type:                      Size: 4"                      Material: Carbon Steel  
 Variance:                      Age:                      Contents:

Integrity Summary

Failures:                      Spills:                      Repairs Made:  
 Coatings:                      H2S:                      Cathodic Protection:

Pressure Testing

Witnessed:                      Test Result:                      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☐ 1103. Abandonment

Comment: Out of service line running lease road in front of K31E location entrance.

Corrective Action: Communicate with COGCC inspector Longworth what is status of this line and plans for this flowline.

Date: 06/03/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103722	Flowline inspection 701103704 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6119714">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6119714</a>