

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2023

Submitted Date:

05/12/2023

Document Number:

707800364

**FIELD INSPECTION FORM**Loc ID 324673 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 28780

Name of Operator: FAHEY OIL &amp; GAS

Address: 93 SOUTH COUNTY ROAD 159

City: STRASBURG State: CO Zip: 80136

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		dnr_cogccengineering@state.co.us	engineering
Fahey, Dave	303-622-9495	diafahey07@aol.com	Owner Operator

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212387	WELL	PR	05/01/2021	OW	057-06280	STATE 12-1	SI

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 5/10/2023, I, Inspector Scott Ramsey, conducted a routine inspection at Fahey State 12-1, at Location # 324673 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed well pump jack not operating and electric motor disconnected at time of inspection. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area.

Previous Inspector has C/A's for tubing stored, lack of Braden head and Access road over grown and difficult to locate from inspection # 689803371, 689804466 and 689806431 have not been addressed.

During this inspection the following compliance issues were observed:

1. No BMP's installed to prevent sediment migration from occurring on location.
2. Location and access is covered with vegetation.
3. Lease road shows signs of lack of stabilization/compaction.
4. Access road to well is not marked or maintained
5. No API posted on well head
6. No evidence of Braden Head access.
7. Random debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well head signage is lacking information		
Corrective Action:	Provide proper signage per the rule	Date:	06/23/2023

**Emergency Contact Number:**

Comment:	911/303-709-0148		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	05/26/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Barbed wire		
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Oil well head		
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	No evidence of Braden Head access.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection	Date:	05/22/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	212387	Type:	WELL	API Number:	057-06280	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: Well shut in and electric motor for pump jack is disconnected at tme of inspection									
Corrective Action: _____ Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1.No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.  
 2. Location and access is covered with vegetation.  
 3. Lease road shows signs of lack of stabilization/compaction.  
 4. Access road to well is not marked or maintained

Corrective Action: **Install, maintain or repair required BMPs**

Date: 06/23/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403402394	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113831">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113831</a>
707800370	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113823">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113823</a>