

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location #334743



SW Corner of Location – Photo #03578



NW Corner of Location – Photo #03579

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location #334743



NE Corner of Location – Photo #03580



SE Corner of Location – Photo #03581

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location #334743



Wellheads – Photo #03582



Separators – Photo #03586

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location #334743



Tank Battery – Photo #03587



Open-Ended Load Line – Photo #03591

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location #334743



Debris in Tank Battery – Photo #03592



Unsecured Load Line – Photo #03593

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location #334743



Sediment Encroaching on Equipment – Photo #03589

Sediment Encroaching on Equipment – Photo #03590

TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location #334743



Lease Road Lacks Stabilization – Photo #03595



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03598