



Inspection Photos
Spill REM 29154
Inspection
Date:5/18/2023

All Photos taken
by Kris Neidel

Photo #1 COGCC staff was told that this is a remaining flowline. Staff was told that Form 44 was in process for this line. The area below this line should be sampled as a part of REM 29154, in addition to where the line is cut and abandon.





Inspection Photos
Spill REM 29154
Inspection
Date:5/18/2023

All Photos taken
by Kris Neidel

Photo #2 looking east, at the northeast corner of location.



Inspection Photos
Spill REM 29154
Inspection
Date:5/18/2023

All Photos taken
by Kris Neidel

Photo #3 close up of photo #2 showing pipeline marker.





Inspection Photos
Spill REM 29154
Inspection
Date:5/18/2023

All Photos taken
by Kris Neidel

Photo #4 some staining on the ground near flowline riser, at wellhead.