

**POC-I LLC
Iles Dome Unit 24
Location #312848**



Access road from entrance to location



Entrance to location from access road

POC-I LLC
Iles Dome Unit 24
Location #312848



Need API Number, Emergency contact and access information



Random debris

POC-I LLC
Iles Dome Unit 24
Location #312848



Production casing? No visible Bradenhead valve.



No labels or wildlife protection

**POC-I LLC
Iles Dome Unit 24
Location #312848**



Random debris



Random debris

**POC-I LLC
Iles Dome Unit 24
Location #312848**



Random debris



Random debris

**POC-I LLC
Iles Dome Unit 24
Location #312848**



Random debris



Random debris

POC-I LLC
Iles Dome Unit 24
Location #312848



Stained soil



Stained soil

**POC-I LLC
Iles Dome Unit 24
Location #312848**



Lack of stabilization and sediment migration



Location erosion and sediment migration

**POC-I LLC
Iles Dome Unit 24
Location #312848**



Lack of stabilization



Location erosion at access road entrance

**POC-I LLC
Iles Dome Unit 24
Location #312848**



View from Southeast corner



View from Southwest corner

**POC-I LLC
Iles Dome Unit 24
Location #312848**



View from Northwest corner



View from Northeast corner