

Interim Reclamation and Stormwater Inspection

Date: 05/17/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 468967

Inspection Document #: 708200266

Weld County, CO

NENE Section 17 T9N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 1. Facing north from the eastern side of the location. Undesirable weedy vegetation (e.g. kochia and russian thistle) was observed to be growing throughout the perimeter of the location in the stormwater ditch system. Management of undesirable vegetation is required to prevent spread to adjacent lands.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 2. Facing northeast at sediment trap on the northern end of the location. See comments in Photo 1.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 3. North side of location; rill erosion and undesirable weedy vegetation observed. See comments in Photo 1.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 4. Facing northwest at the northwest corner. See comments in Photo 1.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 5. Road drag/maintainer stored on location. Storage of equipment, supplies, etc on location is prohibited.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 6. Middle tank did not have any netting installed to prevent wildlife entry.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 7. Facing west at the interim reclamation area and topsoil stockpile. Stockpile had evidence of equipment tracking for short term stabilization. The Operator shall continue to comply with interim reclamation timing requirements.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 8. Facing south towards interim areas; see comments in Photo 7.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 9. From the western portion of the production area. Portions of the production area do not appear stabilized with evidence of rill erosion and sediment deposition in the stormwater ditches. Additional stormwater BMP maintenance will need to be performed.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 10. See comments in Photo 9.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 11. See comments in Photo 9.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 12. See comments in Photo 9.

Inspection Photos
Location Name: Timbro 1717
Location ID: 468967



Photo 13. See comments in Photo 9.