

Inspection Photos

May 17, 2023

Operator: POC-I LLC - #10386

Location ID: 423762

Location Name: ILES DOME UNIT/38

Inspection Document #: 702801533

Moffat County, CO

NWSE Section 22 T4N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ILES DOME UNIT/38
Location ID: 423762



Photo 1. Photo taken from the location entrance to the north shows an overview of the location. Note storage of supplies, equipment and debris.



Inspection Photos
Location Name: ILES DOME UNIT/38
Location ID: 423762



Photo 2. Photo taken from the location entrance to the south shows an overview of the location. Note storage of supplies, equipment and debris.



Inspection Photos
Location Name: ILES DOME UNIT/38
Location ID: 423762



Photo 3. Photo shows storage of leaking chemical drums. No wildlife protection BMPs present to prevent entry into secondary containment.



Inspection Photos
Location Name: ILES DOME UNIT/38
Location ID: 423762



Photo 4. Photos show staining at the cathodic protection unit.



Inspection Photos
Location Name: ILES DOME UNIT/38
Location ID: 423762



Photo 5. Photo shows an anchor to the northeast of the location. All equipment, both on and offsite must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801533

Inspection Photos
Location Name: ILES DOME UNIT/38
Location ID: 423762



Photo 6. Photos show list B noxious weeds Canada thistle (left) and whitetop/hoary cress (right).



Inspection Photos
Location Name: ILES DOME UNIT/38
Location ID: 423762



Photo 7. Photos show the cut slope is unstable. Vegetation is pedestaled with exposed roots. Erosion appears to be migrating upslope/backwards, undercutting into undisturbed reference areas. Rill erosion is occurring.

Inspection Photos
Location Name: ILES DOME UNIT/38
Location ID: 423762



Photo 8. Photos show the cut slope is unstable. Vegetation is pedestaled with exposed roots. Erosion appears to be migrating upslope/backwards, undercutting into undisturbed reference areas. Rill erosion is occurring.