

Inspection Photos

API: 043-40000

Operator: JAVERNICK OIL

Inspection Date: 5/22/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-40000 | Date: 5/22/2023

Inspection Photos



Photo 1. Facing east at the abandoned well site. There is an abandoned powerpole that remains which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 5/22/2023

Inspection Photos



Photo 2. Facing east toward the location. There is gravelly soils and debris that remain and the location is not reclaimed. There is no vegetation growth in this area of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 5/22/2023

Inspection Photos



Photo 3. There is cable and various debris that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 5/22/2023

Inspection Photos



Photo 4. Facing north toward the location. There wood plank debris and oily soils that were never cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 5/22/2023

Inspection Photos



Photo 5. There is a bridge timber used for the pumpjack base that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 5/22/2023

Inspection Photos



Photo 6. There are signs of erosion and soils are not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 5/22/2023

Inspection Photos



Photo 7. There are cement blocks that remain which need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 5/22/2023