

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad

Location ID: 414794



Photo # 8419 From entrance to location



Photo # 8420 From entrance to location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8422 Location



Photo # 8423 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad

Location ID: 414794



Photo # 8424 Location



Photo # 8501 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8471 Meter calibration info not conspicuously posted



Photo # 8472 Meter calibration info not conspicuously posted

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8473 Meter calibration info not conspicuously posted



Photo # 8474 Meter calibration info not conspicuously posted

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8481 Valve on bradenhead leaking fluid onto ground



Photo # 8483 Valve on bradenhead leaking fluid onto ground



Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8433 Valve on bradenhead leaking fluid onto ground



Photo # 8436 Valve on bradenhead leaking fluid onto ground



Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8426 Unused equipment



Photo # 8427 Unused equipment

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8490 Unused equipment



Photo # 8495 Unused equipment



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad

Location ID: 414794



Photo # 8442 Chemical tank containment 1 full of fluid/failure to maintain chemical BMP's



Photo # 8447 Chemical tank containment 2 full of fluid/failure to maintain chemical BMP's

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8430 Stained soils & gravel



Photo # 8437 Stained soils & gravel

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794




Photo # 8439 Stained soils & gravel



Photo # 8465 Stained soils & gravel

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8491 Stained gravel



Photo # 8492 Stained gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad

Location ID: 414794



Photo # 8493 Stained gravel



Photo # 8449 Debris



Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8450 Debris




Photo # 8470 Debris



Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC MDP 2 Pad
Location ID: 414794



Photo # 8497 Debris