

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2023

Submitted Date:

05/25/2023

Document Number:

699805641

**FIELD INSPECTION FORM**

Loc ID 323833 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210919	WELL	PR	01/29/1998	GW	045-06677	MOBIL GV 40-33	PR

**General Comment:****COGCC Inspection Report Summary**

On 5/22/23 at approximately 14:30 hours, I, Inspector Corey De Paolo,

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW.

Location #323833 Garfield County Colorado

While there, I observed normal production operations.

Refer to document #699805482 inspection conducted on 3/17/23. Previous corrective actions have not been completed.

During this inspection the following compliance issues were observed:

1) Calibration cards not conspicuously posted with a previous CA date of 3/31/23.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.

This is a summary of the inspection report

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Gas Meter Run	# 1			
Comment:	Calibration cards not conspicuously posted.			
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration		Date:	06/01/2023
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:	Well on plunger lift			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Chemical tank			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Taylor plugs located on braden heads. All braden head valves are accessible.			
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	210919	Type:	WELL	API Number:	045-06677	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Compaction						
Ditches						
		Culverts				
		Ditches				
		Culverts				
Berms						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Refer to Equipment for corrective actions.	depaoloc	05/24/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805642	Photos for Insp. #699805641	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125388">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125388</a>