


**Inspection Photos**  
**Location Name: Fabrizius 33-34**  
**Location ID: 302848**



**Photo 1 – Pumping Unit**



**Photo 2 – Wellhead – Stained Soil**

**Inspection Photos**  
**Location Name: Fabrizius 33-34**  
**Location ID: 302848**



**Photo 3 – Engine House**



**Photo 4 – Stained Soil**



**Inspection Photos**  
**Location Name: Fabrizius 33-34**  
**Location ID: 302848**



**Photo 5 – Gas Engine**



**Photo 6 – Stained Soil**

**Inspection Photos**  
**Location Name: Fabrizius 33-34**  
**Location ID: 302848**



**Photo 7 – Stained Soil**



**Photo 8 – Stained Soil**



**Inspection Photos**  
**Location Name: Fabrizius 33-34**  
**Location ID: 302848**



**Photo 9 – Gate in disrepair**



**Photo 10 – Sign at Entrance**