

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2023

Submitted Date:

05/22/2023

Document Number:

694500572

**FIELD INSPECTION FORM**Loc ID 312985 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Weinert, Dave	307-577-5329	davew@kirkwoodcompanies.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223184	WELL	PR	09/01/2020	GW	081-06546	MAUDLIN GULCH UNIT 24	EI

**General Comment:**

on 3/14/2023 COGCC staff, Kris Neidel inspected the Maudlin Gulch #24. Weather; 65 degrees, , the creek and ditches were full with spring runoff. Surface water was flowing on and accross the access roads. The well has been reported as PA, no wellhead marker was present the only observable sign of production were; the pad, one flowline riser, flowline marker. Corrective Actions: Samples for REM #29154 should include those on the approved Form 27 and below removed equipment at the flowline riser. NO cement pads shall be incorporated in reclaim or left on pad after abandonment. See attached Photos.



**Environmental****Spill/Remediation:**

Comment: When Project 29154 was approved, it was not stated that a flowline riser was present south of the wellhead and cement from production phase was near flowline.

Corrective Action: Samples for REM #29154 should include those on the approved Form 27 and below removed equipment at the flowline riser. NO cement pads shall be incorporated in reclaim or left on pad after abandonment.

Date: 10/01/2023

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403409604	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121078">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121078</a>
694500573	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121064">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121064</a>