

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2023

Submitted Date:

05/25/2023

Document Number:

696304945

FIELD INSPECTION FORMLoc ID 302848 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10575

Name of Operator: 8 NORTH LLC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , | | Inspections@civiresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 301223 | WELL | SI | 01/01/2023 | OW | 123-29929 | Fabrizius 33-34 | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------------|--|--|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | Date: _____ | | |

| | | | |
|---------------------------|--|-------|------------|
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Stained Soil at Wellhead, Exhaust and Gas Engine; see photos | | |
| Corrective Action: | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." | Date: | 06/09/2023 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Gas Engine | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 301223 | Type: | WELL | API Number: | 123-29929 | Status: | SI | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: <input type="text" value="SI"/> | | | | | | | | | |
| Corrective Action: <input type="text"/> Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| Routine Field Inspection. Stained Soil at Wellhead, Gas Engine and Exhaust | petrie | 05/25/2023 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403414138 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126122 |
| 696304953 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126111 |