

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2023

Submitted Date:

05/25/2023

Document Number:

696304950

**FIELD INSPECTION FORM**Loc ID 413933 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10575

Name of Operator: 8 NORTH LLC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
| ,            |       | Inspections@civiresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 411968      | WELL | PR     | 03/01/2023  | OW         | 123-30324 | FABRIZIUS 33-14 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | Adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |             |  |  |
|---------------------------|-------------|--|--|
| Emergency Contact Number: |             |  |  |
| Comment:                  |             |  |  |
| Corrective Action:        | Date: _____ |  |  |

|                           |  |       |            |
|---------------------------|--|-------|------------|
| <b>Good Housekeeping:</b> |  |       |            |
| Type                      | OTHER  |       |            |
| Comment:                  | Stained Soil at Wellhead, Gas Engine, and Exhaust; see photos  |       |            |
| Corrective Action:        | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." | Date: | 06/09/2023 |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |           |       |  |
|--------------------|-----------|-------|--|
| <b>Fencing/:</b>   |           |       |  |
| Type               | PUMP JACK |       |  |
| Comment:           | Panels    |       |  |
| Corrective Action: |           | Date: |  |

|                    |                                  |       |                 |
|--------------------|----------------------------------|-------|-----------------|
| <b>Equipment:</b>  |                                  |       | corrective date |
| Type: Pump Jack    | # 1                              |       |                 |
| Comment:           |                                  |       |                 |
| Corrective Action: |                                  | Date: |                 |
| Type: Prime Mover  | # 1                              |       |                 |
| Comment:           | Gas Engine                       |       |                 |
| Corrective Action: |                                  | Date: |                 |
| Type: Bradenhead   | # 1                              |       |                 |
| Comment:           | Appears to be plumbed to surface |       |                 |
| Corrective Action: |                                  | Date: |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Venting:</b>    |  |       |  |
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Flaring:</b> |  |  |  |
| Type            |  |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 411968 | Type: | WELL | API Number: | 123-30324 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |       |      |             |           |         |    |               |    |
| Comment:             |        | PR    |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <a href="#">Routine Field Inspection. Statined Soil at Wellhead, Gas Engine and Exhaust</a> | petrie | 05/25/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403414139    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126123">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126123</a> |
| 696304952    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126114">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126114</a> |