

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2023

Submitted Date:

06/01/2023

Document Number:

699805662

**FIELD INSPECTION FORM**

Loc ID 334920 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270608	WELL	PR	12/04/2003	GW	045-09567	PA 531-6	PR
270609	WELL	PR	07/16/2004	GW	045-09568	PA 31-6	PR
270610	WELL	PR	07/12/2004	GW	045-09569	PA 331-6	PR
270611	WELL	PR	07/21/2004	GW	045-09570	PA 431-6	PR

**General Comment:**

COGCC Inspection Report Summary  
 On 5/31/23 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC PA-67S95W /6NWNE. Location #334920 Garfield County Colorado  
 While there, I observed normal production operations.  
 During this inspection the following compliance issues were observed:

1) Meter calibration card is not conspicuously post with a CA date of 6/11/23.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of the inspection report

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 4		
Comment:	Taylor plugs located on braden heads. All braden head valves are accessible		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	Meter calibration card is not conspicuously post.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter		Date: 06/11/2023
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	270608	Type:	WELL	API Number:	045-09567	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	270609	Type:	WELL	API Number:	045-09568	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	270610	Type:	WELL	API Number:	045-09569	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	270611	Type:	WELL	API Number:	045-09570	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Sediment Traps						
Berms						
		Ditches				
		Berms				
Ditches						
		Gravel				
		Compaction				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Storm water for comments</a>	depaoloc	06/01/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805663	Photos for Insp. #699805662	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132576">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6132576</a>