

Interim Reclamation and Stormwater Inspection

Date: 05/26/2023

Operator: FUNDARE RESOURCES OPERATING
COMPANY LLC - 10773

Location ID: 433999

Inspection Document #: 708200290

Weld County, CO

NESE Section 27 T10 R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999



Photo 1. Southern interim/topsoil stockpile. During this inspection Staff observed that the interim areas are not progressing towards reclamation standards with evidence of non-uniform vegetation cover resulting in areas of bare soil and undesirable vegetation (e.g. kochia) was observed growing throughout. Additional reclamation activities are required in order to meet Rule 1003 standards.

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999



Photo 2. Topsoil stockpile. See comments in Photo 1.

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999



Photo 3. Eastern interim area. See comments in Photo 1.

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999



Photo 4. Northern interim area. See comments in Photo 1.

Inspection Photos
Location Name: Razor 27I Pad
Location ID: 433999



Photo 5. Southern Interim areas. See comments in Photo 1.



Photo 6. During this inspection, Staff observed that cut banks towards the northwest corner of the location are experiencing rill erosion and do not appear to be properly stabilized. Repair/maintenance of stormwater BMPs should be implemented to stabilize the areas experiencing erosion.

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999



Photo 7. Northern end of location. Debris observed during this inspection will need to be removed. Unmarked hose/tubing coming from ground.

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999



Photo 8. Eastern side of location. See comments in Photo 7.

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999




Photo 9. Eastern side of location. See comments in Photo 7.

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999



Photo 10. Apparent hydrocarbon leak observed within secondary containment on the west side of the location. Properly dispose of oily waste in accordance with 905.e. Additionally, Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Inspection Photos
Location Name: Razor 271 Pad
Location ID: 433999



Photo 11. See comments in Photo 10.