

Inspection Photos

API: 055-06314

Operator: OXY USA INC

Inspection Date: 6/1/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06314 | Date: 6/1/2023

Inspection Photos



Photo 1. Facing toward the SMU 4-23 well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06314 | Date: 6/1/2023

Inspection Photos



Photo 2. The wellhead is partially excavated and there is oil stained soils at red arrow that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06314 | Date: 6/1/2023

Inspection Photos



Photo 3. There is a dripping leak coming from the chemical tank line.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06314 | Date: 6/1/2023

Inspection Photos



Photo 4. There is no labeling at the tank and there is no lid on the tank



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06314 | Date: 6/1/2023