

Inspection Photos

Loc: 333348

Operator: OXY USA INC

Inspection Date: 6/1/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 1. Drone aerial photo facing northeast at the Drill site 3 compressor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 2. Previous Drone aerial photos taken on 4/10/2023. Facing northeast at the Drill site 3 compressor. There was a leak that has blackened the facility and areas of the ground and sprayed out to the northeast off the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 3. Facing north at the Drill site 3 compressor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 4. The is still stained soils along the east side of the compressor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 5. There are still numerous areas of impacted soil from the spill that have not been cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 6. Facing toward the facility where leak occurred. The facility still remains blackened from the spil. There is still oil stained soils at the base of the facility shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 6. Facing toward the west side of the facility. It appears stormwater has moved impacted material down gradient. There is a line of oil staining at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 6. Facing back south toward the facility where spill occurred.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 9. Facing northeast off the location where spill had drifted off the location. There are no perimeter stormwater controls around the area of the spill. The vegetation is growing in this area however, soils and vegetation remain blackened from the spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023

Inspection Photos



Photo 10. The vegetation, brush, trees, still remain blackened from the spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 6/1/2023