

Photo 1



Location of the Gulley #1-D Off0-location Flowline

Photo 2



Gulley #1-D flowline riser point

Gulley #1-D Off-Location Flowline Removal
PADCO, LLC
Remediation Project #28912

Photo 3



Gulley #1-D Flowline Excavation

Photo 4



Sample Point G1b (observed stained soil around fiberglass flowline collar)

Photo 5



Sample point G1b (excavation of contaminated soil and samples G1b2 for closure)