

# Inspection Photos

API: 055-06316

Operator: OXY USA INC

Inspection Date: 6/1/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06316 | Date: 6/1/2023

## Inspection Photos



**Photo 1.** Facing south along the access road. There are signs of erosion along the steep grade of the road. Stormwater should be diverted off the road to reduce erosion. Previous corrective action is not completed.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06316 | Date: 6/1/2023



## Inspection Photos



**Photo 2.** Facing back north the steep grade of access road. Stormwater is not being diverted off the road which is causing erosion of the road. Stormwater should be diverted toward red arrow and into a sediment trap.



**Photo 3.** This sediment trap is completely full sediment and needs to be maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06316 | Date: 6/1/2023



## Inspection Photos



**Photo 4.** Facing southwest near the location. Sediment is being deposited offsite in this area from erosion of the road. This sediment trap is completely full sediment and needs to be maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06316 | Date: 6/1/2023



## Inspection Photos



**Photo 5.** There is no labeling of the white chemical container.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06316 | Date: 6/1/2023