

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2023

Submitted Date:

06/05/2023

Document Number:

702501412

**FIELD INSPECTION FORM**Loc ID 312953 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen	(505) 326-2659	notices@rlbayless.com	
Thomas, John	(505)326-2659	jthomas@rlbayless.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223008	WELL	SI	10/01/2022	OW	081-06370	DEER CREEK STATE 1 (16-4-91)	SI

**General Comment:****COGCC Inspection Report Summary**

On Monday, 06/05/2023, Inspector Kirby Burchett, conducted a routine field inspection at Robert L Bayless Producer LLC on the Deer Creek State 1 (16-4-91) well, Location #312953, in Moffat County, Colorado.  
This location is within or in close proximity to a CPW District with High Priority, NSO, and Density Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. Random debris.
2. Unlabeled propane tank.
3. Insufficient Stormwater BMPs.
4. Leaks on pumping unit with stained soils.
5. Production tank heat tube open to wildlife.
6. Tank berm insufficient in case of spill.
7. Unmarked guy line anchors.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

The subreport 'OperatorInfo2' could not be found at the specified location \\10.14.12.103\efFormReports\Insp\InspLocation-2.rdlc. Please verify that the subreport has been published and that the name is correct.



The subreport 'InspRecPit' could not be found at

The subreport 'rptInsp14' could not be found at the

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501413	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6136406">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6136406</a>